


Ceiling slab waterproofing repair
Initial assessment



Ceiling slab waterproofing repair
Point of seepage



Ceiling slab waterproofing repair
Our team chased all cracks



Ceiling slab waterproofing repair
After removing patch mortar, we found an old electrical box



Ceiling slab waterproofing repair
Initial coat of CN2000B® by trowel



Ceiling slab waterproofing repair
Final coat of CN2000C® and CN2000D®

