

Client: Ellis Don / Target Canada

Topic: Traffic Marking Obliteration

Situation

Our client identified:

- ∴ The traffic markings painted on the asphalt surface in front of the store presented a slip-and-fall hazard when wet.

Challenges

The challenges facing us were in:

- ∴ Removing the existing markings while leaving behind the 'STOP' marking.
- ∴ Completing the work at night during the mall closure hours.
- ∴ Ensuring the parking lot was swept prior to opening the following day.



Actions

The actions we took to address these challenges were:

- ∴ Use of our non-destructive abrasive blasting approach to remove only the hazardous markings, while leaving others in place.
- ∴ Our team arrived and performed the work after closing hours so there was no disruption to the customers during business hours.
- ∴ Parking lot was swept clean prior to the business opening the following day.

Results

Our actions resulted in:

- ∴ Asphalt integrity remained intact.
- ∴ Slip-and-fall hazard was eliminated.



For additional information, or to discuss your requirements, please contact:

Kelso Industrial Group ♦ 575 Industrial Drive ♦ Milton, ON L9T 5E1 ♦ 877-462-7639
info@kelsoindustrial.com ♦ www.kelsoindustrialgroup.com