

Canadian Tire, Toronto, Ontario
Structural steel beams corroded due to water leakage



Canadian Tire, Toronto, Ontario
Structural steel beams corroded due to water leakage



Canadian Tire, Toronto, Ontario
Structural steel beams corroded due to water leakage



Canadian Tire, Toronto, Ontario
Structural steel beams corroded due to water leakage

