

# Propane Tank Farm

## Case study – 2015

The Customer was experiencing a failure in the coating applied to the exterior of 5 large propane holding tanks. They contacted Kelso to blast the tanks to bare metal to prepare for repainting.

### The Challenges

To safely complete the work, Kelso used a wet abrasive blasting method to ensure no sparking could be caused. The wet blasting also significantly reduced the migration of any blasting media towards the Company's main office building.

Work was completed safely from elevated work platforms as all employees are certified under the laws of the Province of Ontario for working at heights as well as operating elevated work platforms.

### Results

All work was successfully completed in the timeframe required by the customer to repaint the tanks.



### Client Profile

**Industry:** Propane Distributor

**Geography:** Canada

**Services provided:**  
Wet Abrasive Blasting